

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



INSPECTION REPORT

Michael O. Leavitt Governor

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: Complete: XXX Exploration: Inspection Date & Time: 8/25/99 / 8:30a.m.-2:00p.m.

Date of Last Inspection: 7/22/99

Mine Name: <u>Deer Creek Mine</u> County: <u>Emery</u> Permit Number: <u>ACT/015/018 x 5</u> Permittee and/or Operator's Name: <u>PacifiCorp</u> Business Address: <u>P.O. Box 310, Huntington, Utah 84528</u>						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Dennis Oakley						
State Officials(s): Pete Hess Federal Official(s): None						
Weather Conditions: Partly Cloudy, Some Showers, 80's						
Existing Acreage: Permitted-17,826.85 Disturbed-95.79 Regraded_Seeded_Bonded-95.79						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/_Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liabilityyear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate
 to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]		[]	[]
2.	SIGNS AND MARKERS	XX	\Box	Ħ	1 7
3.	TOPSOIL	[XX]	Ħ	Ħ	11
4.	HYDROLOGIC BALANCE:	<u> </u>			
a.	DIVERSIONS	[XX]	F 1	[XX]	[1]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	<u>[XX]</u>		[XX]	Ħ
c.	OTHER SEDIMENT CONTROL MEASURES	XX	Π	XX	
d.	WATER MONITORING	XX	i i	XX	Ħ
e.	EFFLUENT LIMITATIONS	XX	īī		īi
5.	EXPLOSIVES	[XX]	Π	īī	Π
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[XX]	īī	Ti.
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	ĪXXI	[]	$\overline{[XX]}$	i i
8.	NONCOAL WASTE	XXI	īī		Ti
9.	PROTECTION OF FISH, WILDLIFE AND			_	_
	RELATED ENVIRONMENTAL VALUES	\Box	[]	[]	[]
10.	SLIDES AND OTHER DAMAGE	<u>[XX]</u>		$\overline{[XX]}$	
11.	CONTEMPORANEOUS RECLAMATION		$\overline{[XX]}$		i i
12.	BACKFILLING AND GRADING	ī	$\overline{[XX]}$	Π	Ti.
13.	REVEGETATION	Ti .	XX	īi	ī ī
14.	SUBSIDENCE CONTROL	XX		īi	Ti.
15.	CESSATION OF OPERATIONS	[]	$\overline{\mathbf{X}}\mathbf{X}1$	īī	ΪĨ
16.	ROADS:	_		_	_
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[]	[XX]	[]
b.	DRAINAGE CONTROLS	XX	Π	<u> </u>	Πī
17.	OTHER TRANSPORTATION FACILITIES	XX	ii .	Ħ	Ti.
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	XX	i i	Ti .	Ti.
19.	AVS CHECK (4th Quarter-April, May, June)(date)	[XX]	īi	ī	
20.	AIR QUALITY PERMIT	[XX]	Π	ii	Ħ
21.	BONDING & INSURANCE	[XX]	īī	īī	īī

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 8/25/99

(Comments are Numbered to Correspond with Topics Listed Above)

4a. HYDROLOGIC BALANCE: DIVERSIONS

The diversion ditch on the eastern edge of the parking lot area of the main mine facilities has silted in; it was carrying a fairly significant flow when observed this day. It was recommended to Mr. Oakley that the ditch be redefined for future events.

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Second quarter impoundment inspections for the mine site and waste rock disposal sediment ponds were conducted on June 11, 1999. No hazardous conditions were reported. The information was forwarded to the SLO-UDNR/OGM on July 9, 1999.

4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Intense storms in the vicinity of the active waste rock site have damaged several of the silt fences in the area, rendering them incapable of functioning. Sediment loading has pushed over several fences. Basins have been completely filled and bypassed. A high water mark in one of the undisturbed drainages is indicative of incredibly high flow volumes for the area.

The permittee has taken extraordinary measures to repair these fences as quickly as possible; however, storm frequency and intensity has not diminished as of late. The silt fence which runs parallel with the toe of the northern slope is a particular problem area. Undisturbed area drainage is running over this fence, destroying it. The permittee is evaluating the current design to see if additional measures may be worth while.

It may be advantageous for the permittee to install a rain gauge at the active waste rock site to determine storm intensity. If the design event for the site is exceeded, then the permittee should not have to spend additional money to enhance the north slope design.

4d. HYDROLOGIC BALANCE: WATER MONITORING

Discharge monitoring reports for the months of April, May and June were reviewed. All reports were submitted in a timely fashion. UPDES point 002A had an exceedance in iron of 0.1 mg/l; same was reported to DEQ/DWQ in normal fashion.

The Utah Division of Water Quality sampled effluent from UPDES 001A on April 13, 1999. Based on that Agency's response to the permittee, no problems were noted with any of the test parameters.

The second quarter water monitoring report for the Deer Creek Mine was submitted to the SLO-UDNR/OGM on August 12, 1999. There were no unusual conditions observed in the data which was reviewed.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 8/25/99

(Comments are Numbered to Correspond with Topics Listed Above)

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The second quarter waste rock site inspection(s) for the active waste rock site, the original site, and the Elk Canyon coal storage pad were conducted by Mr. John Christensen, P.E., and Mr. Rick Cullum on June 16, 1999. No hazardous conditions or other unusual circumstances were reported for any of the three sites. The reports were P.E. certified by Mr. Christensen.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chuck Semborski (PacifiCorp)

Given to: Joe Helfrich (DOM)

Filed to: Price Field Office

Date: September 2, 1999

Inspector's Signature: #46

Peter Hess